| Project Name: | Locomotive | Workshop, | South Eveleigh |
|---------------|------------|-----------|----------------|
|---------------|------------|-----------|----------------|

| Enquir 5 | Date | Enquiry or complaint | Details of enquiry or complaint | Follow Up | |
|-------------|----------------|-------------------------|--|--|--|
| 1 | 4.09.19 | Complaint | Saw cutting in the hall area. | Mirvac installed noise and vibration monitors (4 in total). It was also clarified that there was a lease agreement in place which allowed noisy works to be carried out between the hours of 7-10am Monday to Friday and 7-1pm Saturdays. Thresholds for noise and vibration are in place for works outside of these hours. | |
| 2 | 5.09.19 | Complaint | Saw cutting in the hall area. | Mirvac installed noise and vibration monitors (4 in total). It was also clarified that there was a lease agreement in place which allowed noisy works to be carried out between the hours of 7-10am Monday to Friday and 7-1pm Saturdays. Thresholds for noise and vibration are in place for works outside of these hours. | |
| 3 | 25.10.19 | Enquiry | Heritage tours | A community group wanted to organise a tour of the Locomotive Workshop for 30 people. Mirvac advised that heritage tours would resume late 2020. | |
| 4 | 07.01.20 | Enquiry | Purpose of the erection of the Tower Crane in Bay 4 | Clarification of the reason the Tower Crane was being installed, including faciliation of new fitout for commercial and retail tenants, as well as heritage exhibitions. | |
| 5 | 17.01.20 | Enquiry | Request for filming permit. | Filming permit issued. | |
| 6 | 22.01.20 | Enquiry | Request for tour of the Locomotive Workshop. | Advised that Locomotive Workshop under construction, Yerraingin rooftop sugested as an alternative. | |
| 7 | 29.01.20 | Enquiry | Ensure that the poor working conditions of Locomotive Workshop workers is reflected in heritage interpretation. | Confirmed that heritage interpretation would accurately reflect the poor working conditions in the Locomotive Workshops. | |
| 8 | 31.01.20 | Complaint | Request to extent the period of noisy works credit. | The asset management team are in conversation with Post Op to resolve this issue. | |
| 9 | 3.2.20 | Complaint | Leaking roof in Bay 14. | Mirvac coordinated repairs to rectify the issue. | |
| 10 | 21.5.2020 | Enquiry | Request to move the Ausgrid power outage date due to operational requirements | Meeting held on 25 May to discuss the use of a generator to ensure operational requirements can be met during power outage. | |
| | | | | The project team hold weekly meetings with Post Op and Eveleigh Works to work through any issues and provide updates on the construction program. This is an effective way to minimise complaints and enquiries and ensure open lines of communications between key tenants that remain in the Locomotive Workshop during the redevelopment | |
| 11 | 5.6.2020 | Complaint | Ensure that workers near tenancies in the Locomotive Workshop are announced to the tenants prior to undertaking works and sanitise during COVID | Workers will not enter any areas belonging to a tenant without prior agreement with the tenant. Apologies if the workers were too close for comfort to the tenancy in question. | |
| 12 | 3.7.2020 | Enquiry | Request to tender for the KK Eatery construction | Mirvae will construction inhouse | |
| 13 | 23.7.2020 | Complaint | Noise complaint from tenant of Locomotive Workshop about noise coming from Bay 15 from 10am-11am | Operations were within compliant limits however all works were stopped to accommodate Post Op Group | |
| 14 | 18.8.2020 | Complaint | Fibre was cut out for tenant of Locomotive Workshop | Fibre was restored immediately | |
| 15 | 28.02.202 2 | Complaint | Sinking pavers, located near the pedestrian crossig at the area near data 61 | In Progress | |
| 16 | 17.01.2022 | Complaint | Sinking pavers, located close to a pedestrian crossing. | Fixed | |
| 17 | 02.22.22 | Complaint | The sprinkler timing has not been adjusted for daylight saving | Fixed | |